

FIG. 1




FIG. 2






FIG. 3






FIG. 4








FIG. 5

SEVENTH STEP



EIGHTH AND
NINTH STEP



COMPLETE

FIG. 6




FIG. 7




FIG. 8






FIG. 9




FIG. 10






FIG. 11




FIG. 12






FIG. 13





FIG. 14






FIG. 15






FIG. 16






FIG. 17




FIG. 18






FIG. 19




FIG. 20






FIG. 21





FIG. 22






FIG. 23




FIG. 24




FIG. 25






FIG. 26a




FIG. 26b







FIG. 27






FIG. 28






FIG. 29




FIG. 30






FIG. 31
(PRIOR ART)





FIG. 32
(PRIOR ART)






FIG. 33a




FIG. 33b






FIG. 34a




FIG. 34b






FIG. 35






FIG. 36




FIG. 37






FIG. 38




FIG. 39a




FIG. 39b





FIG. 39c



PHYSICAL VALUES AND SPUTTER RESISTANCE OF
STRESS RELAXATION LAYER CANDIDATE MATERIAL
(X: OCCURRENCE OF CRACKS, Δ: OCCURRENCE OF WRINKLE,
○: NO ABNORMALITY)